

**Repair Centers
For
LeSharo and Phasar vehicles**

United States and Canada

State: Canada
Repair Facility: Boucher Motors
Street: 310 E. 2nd. Avenue
City, ST, Zip: Vancouver, British Columbia
Phone: 604-873-8361
Fax #: Unknown
Contact Person: Unknown
Road Service #: Unknown
Services Provided: Unknown
Satisfaction (1-10): No reports on customer satisfaction
Brief Comments: Recommended by local Winnebago dealer. No service or experience with them
Submitted By: Submitted by C. Moreland

State: Florida
Repair Facility: Kohls Transmission Service
Street: 44 Mildred Dr. (Across from Edison Mall)
City, ST, Zip: Fort. Meyers, FL
Phone: 941-936-2197
Fax #: Unknown
Contact Person: Unknown
Road Service #: Unknown
Services Provided: Transmissions
Satisfaction (1-10): Customer satisfaction not reported
Brief Comments: Quoted \$1,200 to overhaul my 88LS. Also can install toggle switch controls for selecting shift speeds (by by-passing computer). Found out the Renault, Alliance X-mission Pan Gasket fits LeSharo. (Filter does not. Filter may be cleaned).
Submitted By: Submitted by W.P. GRESH

State: Illinois
Repair Facility: K. & K. Sales, Inc
Street: 6905 Godfrey Rd.
City, ST, Zip: Godfrey, IL, 62035-2821
Phone: 618-4686-5386
Fax #: 618-466-5387
Contact Person: Jim
Road Service #: Unknown
Services Provided: RV Service and Repair

Satisfaction (1-10) 10
Brief Comments: Drove in on the hook, no rear lights, found and replaced loose ground wire. Would only accept \$3.00 as payment.
Submitted By: Submitted by S. Reese

State: Indiana

Repair Facility: Jack Smith & Son, RV Center
Street: 3400 N. Lee Pit Road
City, ST, Zip: Yorktown, IN, 47369
Phone: 317-759-7505 / 800-878-2130 (Parts order)
Fax #: Unknown
Contact Person: Bob Knoblock, Service
Road Service #: Unknown
Services Provided: These folks do a LOT of LeSharo work. Usually 6to 10 units in the parking lot.

Satisfaction (1-10) Contact Arch
Brief Comments: "I called one night at closing time to tell them I was coming in on the hook. Svc. Manager was still there ½ hour after closing. Looked at and stuck in a new sensor which did the trick. Cost, \$54.00. They carry a fairly large inventory of parts".
Submitted By: GCBR@aol.com (Arch)

State: Iowa

Repair Facility: Bob Nath
Street: RR#1, Box 41
City, ST, Zip: Forest City, IA, 50436
Phone: 515-567-3696
Fax #: Unknown
Contact Person: Bob
Road Service #: None
Services Provided: Mechanic for Winnebago
Satisfaction (1-10) 10
Brief Comments: Bob works at Winnebago and does overflow after hours on his farm. Very reasonable while GNR was in progress. Fluid schecked and replaced, general inspection, filters, \$60.00
Submitted By: Submitted by C. Moreland

State: Iowa

Repair Facility: North Central Sales and Service
Street: 16570 370th. St.
City, ST, Zip: Forest City, IA, 50436
Phone: 515-581-3545
Fax #: 515-581-5263
Contact Person: Old Bob and Young Bob Hadachek
Road Service #: Unknown
Services Provided: RV repairs.

Satisfaction (1-10) 10
Brief Comments: Replaced muffler and pipes, \$200.00 during GNR.
Submitted By: Submitted by C. Moreland

State: Iowa

Repair Facility: Mobility RV
Street: I-35 (18 Miles east of Forest City, Iowa).
City, ST, Zip: Hanlonton, IA
Phone: 800-933-7742 (Parts)
Fax #: Unknown
Contact Person: John Stelter, Service Manager.
Road Service #: N/A
Services Provided: Full service of LeSharo & Phasar.
Satisfaction (1-10) Members report satisfaction level of 8-10
Brief Comments: Certified Winnebago repair and service facility. Full parts availability for LeSharo and Phasar.
Submitted By:

State: Kansas

Repair Facility: Central States Special Products
Street: 120 Kansas Avenue
City, ST, Zip: Kansas City, Kansas, 66105
Phone: 913-271-4111
Fax #: 913-621-4963
Contact Person: Ken Colwell, Service Manager
Road Service #: Unknown
Services Provided: Sales and service of Air Conditioning units and Generators.
Satisfaction (1-10) 8
Brief Comments: Onan, Kohler, Generac, Coleman, Duo-Therm dealers. Professional and courteous. Purchased Generac, Impact36G, Generator for my 86 PHGS. Very helpful with compatability testing, final calibration of installed unit. Total cost of unit \$2,156.00.
Submitted By: Submitted by sreese@aol.com

State: Oregon

Repair Facility: Foreign Engine Service
Street: 5811 S. E. Johnson Creek Blvd.
City, ST, Zip: Portland, OR, 97206
Phone: 503-777-2526 or 800-349-3778
Fax #: 503-777-3797
Contact Person: N/A
Road Service #: NA
Services Provided: Complete LeSharo Services
Satisfaction (1-10) 8
Brief Comments: 1987 LSGS lots of restoration work for \$4,772.00
Submitted By: Submitted by C. Moreland

State: Washington
Repair Facility: Valley I-5
Street: 23051 Military Road
City, ST, Zip: Kent, WA, 98032
Phone: 206-824-7170 or 800-562-2323
Fax #: Unknown
Contact Person: Unknown
Road Service #: Unknown
Services Provided: Complete LeSharo services at this time
Satisfaction (1-10) 8
Brief Comments: 1987 LSGS, Auto Transmission replacement \$6,000.00
Submitted By: Submitted by C. Moreland

State: Quebec Canada
Repair Facility: Garage Robert Marleau Enr.
Street: Exit 147 Autoroute 30
423 Petit Coteau
City, ST, Zip: Vercheres, Quebec
Phone: 450-583-2131
Fax #: Unknown
Contact Person: Unknown
Road Service #: Unknown
Services Provided: Specialist in LeSharo, Phasar,Ixtasca
Satisfaction (1-10)
Brief Comments: Haven't done any work with him yet, but plan to have brakes and timing belt done there in October. Has ALL the parts in inventory right down to trim items.
Submitted By: Sam from Austin, Quebec, Canada

State: Montana
Repair Facility: S~works RV Inc./ Specialized Auto Inc
Street: 8002 Timberline Drive
City, ST, Zip: Bozeman, MT 59718
Phone: 888.500.8148
Fax #: 406.587.8148
Contact Person: Greg Erickson
Road Service #: Unknown
Services Provided: Service, parts, info (also conversions)
Satisfaction (1-10) (A number of good comments on conversions.)
Brief Comments: S~Works RV Inc. isn't a bad place to get service, parts or info!
Submitted By: Submitted by Greg cornerguy@sworksrv.com
<<mailto:cornerguy@sworksrv.com>> www.sworksrv.com
<<http://www.sworksrv.com>>